








FLP-5119PM




TECHNICAL DRAWING



TEMP.& WATER PRESSURE REQUIREMENTS





Working Pressure: 1~3 bar




Required Temperature: 5-65°C



Note: Above are the recommended values for getting Conventional Output.









Apply soft cotton cloth



Apply soft cotton cloth




✗ DON'T



✗ DON'T

Don't apply Scrub



Steps & Cleaning agents requirements for Aerator Cleaning.

